

INDIAN HEAD WEST OUTFALL REPAIRS

520 and 538 Wilson Bridge Boulevard



prince
George's
county

MARYLAND

Angela D. Alsobrooks
County Executive




Terry L. Bellamy
DPW&T Director




PROJECT LIMITS & OUTFALL



PRINCE GEORGE'S COUNTY, MARYLAND DEPARTMENT OF PUBLIC WORKS & TRANSPORTATION INDIANHEAD HIGHWAY WEST CHANNEL OUTFALL IMPROVEMENTS 520 WILSON BRIDGE DRIVE OUTFALL




LOCATION MAP
SCALE: 1"=50'




520 WILSON BRIDGE DRIVE OUTFALL
SCALE: 1"=5'

PRINCE GEORGE'S COUNTY, MARYLAND
DEPARTMENT OF PUBLIC WORKS & TRANSPORTATION
INDIANHEAD HIGHWAY WEST CHANNEL OUTFALL IMPROVEMENTS
538 WILSON BRIDGE DRIVE OUTFALL



LOCATION MAP
 SCALE: 1" = 50'



538 WILSON BRIDGE DRIVE OUTFALL
 SCALE: 1" = 5'

POINTS OF CONTACTS DURING DESIGN:

Liz Miller

Chief, Engineering Services Division

Charles Griffith, P.E.

Project Manager

Office: 301-883-5642

Email: EFMiller@co.pg.md.us

CGriffith@co.pg.md.us

POINT OF CONTACT DURING CONSTRUCTION:

Dwight Joseph

Chief, Construction Division

Direct: 301-883-5633

Email: djoseph@co.pg.md.us